

**Section 2 (cce)**

**Manufacturer/Manufacturer**

1. The manufacturer should be a registered company.
2. They should have an office address.
  - (a) They should have the facilities for design of the Boiler or boiler components. The staff should be graduate engineering with sufficient experience.  
They should have the facilities for manufacturer of boiler or boiler components such as
    - (i) Electrical & Gas Welding Sets
    - (ii) Handling facilities
    - (iii) Plate Rolling machine.
3. They should have quality control personnel.
4. The firm should have High Pressure welders qualified under IBR 1950.

....